


EA 01-0C5501 COLLISION DIAGRAM MEN-001-41.8 / 42.3



Dist	COUNTY	ROUTE	POST MILES TOTAL PROJECT	SHEET No.	TOTAL SHEETS
01	MEN	001	41.8/42.3	1	2

LAURA FIELDS 09/03/2020
ASSISTANT TRAFFIC SAFETY ENGINEER DATE

THE STATE OF CALIFORNIA OR ITS OFFICERS
OR AGENTS SHALL NOT BE RESPONSIBLE FOR
THE ACCURACY OR COMPLETENESS OF SCANNED
COPIES OF THIS PLAN SHEET.

- LEGEND**
- FATAL ACCIDENT
 - ⊗ INJURY
 - PROPERTY DAMAGE ONLY
 - ~ OUT OF CONTROL
 - ↺ OVERTURN
 - MOTOR VEHICLE MOVING AHEAD
 - ↪ ○ BROADSIDE

TASAS TABLE B DATES 01/01/2010 THRU 12/31/2019

COLLISION KEY

PM, SIDE OF HIGHWAY, DATE, TIME
WEATHER, LIGHTING, ROADWAY SURFACE
PRIMARY COLLISION FACTOR
TYPE OF COLLISION
PERTINENT / SPECIAL INFORMATION

PM 41.85, NB, 02/15/2013, 1645
CLEAR, DAYLIGHT, DRY
INFLUENCE OF ALCOHOL
HIT OBJECT (DITCH)

PM 41.94, NB, 11/30/2010, 1400
CLOUDY, DAYLIGHT, DRY
IMPROPER TURN (TURNED RIGHT)
HIT OBJECT (EMBANKMENT)
DRIVER INDICATED THE RIGHT TIRES
WENT OFF THE ROADWAY AND THE VEHICLE
PULLED INTO THE BANK.

PM 41.94, NB, 12/04/2010, 2045
CLOUDY, DARK - NO STREET LIGHTS, WET
SPEEDING
HIT OBJECT (EMBANKMENT)
AS THE VEHICLE ENTERED THE TURN,
THE VEHICLE BEGAN TO LOSE TRACTION
ON THE WET ROADWAY AND STARTED
TO SLIDE OUT OF CONTROL. WHEN THE
VEHICLE BEGAN TO LEAVE THE ROADWAY
TO THE EAST, THE DRIVER TURNED TO
THE LEFT AND APPLIED BRAKES.

PM 42.04, SB, 02/23/2013, 1240
CLEAR, DAYLIGHT, DRY
SPEEDING
HIT OBJECT (TREE)
DISTRACTED DRIVER.



PM 41.84, NB, 06/08/2014, 1730
CLEAR, DAYLIGHT, DRY
FAILURE TO YIELD
BROADSIDE
A NB TRAVELING DRIVER WAS
INITIATING A LEFT TURN INTO THE
LOOKOUT. SHE DID NOT SEE SB
TRAFFIC.

NOTE:
NO REPORTED COLLISION PRIOR TO PM 41.84.

NO SCALE

STATE OF CALIFORNIA - DEPARTMENT OF TRANSPORTATION
Caltrans

USERNAME => \$USER
DCN FILE => \$REQUEST

RELATIVE BORDER SCALE
IS IN INCHES



UNIT 0000

PROJECT NUMBER & PHASE

0000000001

LAST REVISION
00-00-00 DATE PLOTTED => \$DATE
TIME PLOTTED => \$TIME